

EPA Region 5 Records Ctr.



287294



August 13, 1985

World Headquarters  
4300 Commerce Court  
Evanston, IL 60632  
Telephone (312) 983-3500  
16 10 02 AM '85  
DIVISION OF LAND  
POLLUTION CONTROL  
STATE  
BOARD OF HEALTH

Mr. John Bonsett  
Public Health Sanitarian  
Johnson County Health Department  
86 West Court Street  
Franklin, IN 46131

Dear Mr. Bonsett:

Enclosed you will find a copy of the final report, prepared by our consultant IT Corp., which details the results of the groundwater investigation conducted at our facility located in Franklin, IN.

The study concludes that, in general, organic groundwater contamination is only of significance beneath the plant property. Off-site contaminant migration is largely intercepted by the large diameter storm sewer found beneath the southern property boundary. This ultimately discharges, with dilution, into Hurricane Creek.

The report is sent to you for information and review, prior to our meeting at 10:00 am on August 27, 1985, in your offices. At that time, the data contained in the report and the conclusions will be discussed in greater detail.

Sincerely,

AMPHENOL PRODUCTS

B. N. Fleischer  
Director,  
Environmental Affairs

cc: Mr. Roy Harbert ✓  
Indiana State Board of Health  
Division of Land Pollution Control  
1330 West Michigan Street  
Indianapolis, IN 46201-1964

Mr. Jeff Eads  
Indiana State Board of Health  
Groundwater Section  
Division of Waste Pollution Control  
1330 West Michigan Street  
P.O. Box 1964  
Indianapolis, IN 46201